Process for second life Mac Pushing info from WipeOS to NetSuite



Once you have successfully booted to WipeOS, follow the steps below:



			WipeC	98 Version: 2.6 Username: admin Client IP: 172,18.148.20
Dun	the iten	n diac	nostics	
Run	the iter	nuiag	SHOSLICS	
Wip	DegS	ACTIONS	S - DIAGNOSTICS ST	ART ALL 1003 SLOGOUT め・
Disks	NVMe	Mobile	Start Hardware Diagnostics	Information Requirements
	Select Hardware Test(s)		• START	P0092344
	Select AllCPU			SAVE ASSET
	MotherboardMemoryHard Drives			REQUEST HELP
	EthernetKeyboardBattery			
	MicrophoneSpeakersUSB			
	✓ Webcam			

- Navigate to the Dagnostics tab
- Set the PO number. That will create a QR code
- Scan the QR code
- Click the Start button

Choose a wipe method

Click the Start button to start the wipe



NVMe

Disks

Mobile

Select Disk Operation

NIST SP 800-88r1 Clear (1-pass)

Information Requirements

П

